

3rd Edition

LatheCity

Safely Working with Benchtop Systems – Booklet II

Working with Exotic Materials

On Lathe & Mill

www.LatheCity.com

Uwe Burghaus



LatheCity

Safely Working with Benchtop Lathes – Booklet II
Booklet 2 – Working with Exotic Materials On Lathe & Mill
1st Ed. January 2012
2nd Ed. July 2012
3rd Ed. February 2013
ISBN-10: 0985136073
ISBN-13: 978-0-9851360-7-9
US Registered copyright: pending

Publisher and author:

Dr. Uwe Burghaus (**LatheCity**)
4465 47th St S
Fargo, ND 58104
USA

Copyright © 2013 Uwe Burghaus, Fargo, North Dakota, USA

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means except as permitted by the United States Copyright Act, without prior written permission of the author. Drawings are included for private and non-commercial use only.

[**www.LatheCity.com**](http://www.LatheCity.com)

sales@lathecity.com

Table of Contents

BOOKLET 2: WORKING WITH EXOTIC MATERIALS ON A LATHE AND MILL

COPYRIGHT

Disclaimer

Brief introductory note

Generic list of pictograms used in LatheCity books

Table of contents

PART 1: SAFETY FIRST.....17

PART 2: TURNING

Alloy Steel	30
Aluminum alloys.....	31
Aluminum vs. steel.....	32
Aluminum Bronze.....	33
Brass.....	34
Carbide	34
Cast Iron.....	36
Cold Pressed Steel C1018.....	36
Ceramics – Macor.....	37
Cork.....	38
Copper.....	38
Free machining materials.....	39
Plastics	39
Rocks	41
Sandwich Structures – Hardened Steel	42
Solid carbide.....	43
Stainless Steel	43
Free machining stainless steel T-303	44
Sterling Silver	45
Sterling Silver hardening	46
Sterling Silver recycling	46
Styrofoam.....	47
Teflon	48
Tomy Bars / Spindle Bars / Parallels.....	48
Grey cast iron	49
Hardened steel, tool steel – A2.....	50
High speed steel- HSS.....	50
Ledloy, 12L14	51
11L17.....	52
Magnetic materials (“super” alloys).....	52
Pure Manganese	53
Titanium.....	54
Wax	55

Wood.....	56
-----------	----

PART 3: MILLING

Plastics	61
Leadloy	61
Working with steel	61
Brass.....	63
Wood.....	63
Milling cast iron.....	63

PART 4: MATERIALS PROPERTIES

Cutting tools and cutting materials	67
Cutting tools on a lathe	
High-speed steel	
Carbide turning tools	
Inserted tip cutters (inserts)	
Standards and nomenclature of turning sets / tool holder	
Fast change tool posts	
Rake angles	
Insert jungle	
Grinding wheels	
Cutting tools on a mill	
Carbide end mills	
Indexable mill cutter	
Two flute vs. four flute cutter	
HSS tools on a mill	
Materials trends and standards	79
What is steel actually?	
A few materials trends	
A few materials properties	
Surface finish	83
Lathe work	
Mill work	
Saws	
Chemistry	
INDEX	91

- A**
- A2, 49
 - Acetal, 39
 - Alloy steel, **30**, 36, 77
 - Aluminum alloys, **31**, 34
 - Aluminum vs. steel, 32
 - Aluminum bronze, 33
 - Aluminum-nickel-cobalt, 52
 - American Society for Testing Materials (ASTM), 48, 53, 78
 - AR, 70
 - AL, 70
 - AISI, 73
 - ANSI, 77
 - ASTM, 48
 - Austenitic stainless steel, 45
- B**
- Brass, **33**, **34**, 39, 61
 - Bronze, 33
 - Bronze vs. Brass, 33-box
 - Brinell, **31**, **51**, 75
 - Brazed cutter, 66
 - BR, 70
 - BL, 70
 - Brazing, 66
- C**
- Casting, **48**, 31
 - Carcinogenic, 30, **38**
 - Casting aluminum, 31
 - Carbide, 34
 - Carbide end mills, 75
 - Cast iron, 36, 48, 61
 - CBN, 35
 - Cold welding 33
 - Crucibles, 35
 - Ceramics, 37
 - Ceramic inserts, 49, 67
 - Cold pressed/rolled steel, 30
 - Cork, 38
 - Copper, 38
 - Colled rolled, 30, 74
 - Chip thickness ratio, 75, 79
 - Chip, 75
 - Chemistry sets, 83
 - Chili exploding, 55
 - Chipbreakers, 72
 - CP GRADE 2, 54
 - Customer Corner, 3
 - Customer Feedback, 10
- D**
- Delrin, 39
 - Dead soft, 45
 - Diamond drill bits, 34
 - Disclaimer, 7
 - Die steel, 50
 - DuPont's, 39, 48
 - Dykem, 83
- E**
- E clip, 42
 - EDM, 35
 - Electric discharge machining, 35

F

- Face shield, 21
- Fast change tool post, 68
- Ferritic Steel, 45
- Free machining materials, 39
- Free machining stainless steel, 44
- Finish, 81
- Full hard, 45
- Filled wiring, 45

G

- Gray cast iron, 77
- Grain structure, 78

H

- Hardening, 30, 46, 49
- Hardness, 32, 46, 51
- HSS, 50
- High Speed Steel, 50, 78
- High carbon steel, 65, 78
- Hot rolled, 78
- Half hard, 45
- Heat-Harden, 46

I

- Inserts, 30, 35, 67, 70, 71
- Inscribed circle, 71

J

- Jewelry, 45

K

- Kiln, 46
- KF flange, 48

L

- LatheCity, 93

- LASER, 24
- Leadloy, 51
- Lead angle, 70

M

- Manganese, 53
- Macor, 37
- Martensitic Steel, 45
- Machinability index, 51, 76
- Makrolon, 40
- Metallic solid solution, 77
- Micrometer, 41
- Morse taper, 30
- Molecular beam epitaxy, 44
- MSDS, 30

N

- Nanoscience, 10, 35, 50, 78
- Nylon, 39
- Nickel alloys, 80
- Nickel-silver , 45

O

- O-rings, 48
- Orthogonal cutting model, 70

P

- Pictograms, 11
- PCBN, 71
- PCD, 71
- Plastics, 39
- Plain steel, 59
- PTFE, 48

Q

- Q.F. flange, 48

R

- Rake angle, 69

Reamers, 50
 Reduced vibration mills, 75
 Rocks, 41
 Rockwell, 79

S

Saws, 83
 SAE, 77
 Sandwich, 42
 Safety, 17
 Safety glasses, 18
 Sheet metal gauge, 47
 Solid carbide, 41
 Soft materials RPM, 46
 Solidification shrinkage, 48
 Soldering, 45
 Stainless steel, 41, 73
 Sterling silver, 43
 Sterling Silver Recycling, 47
 Sterling silver hardening, 45
 Styrofoam, 46
 Suberin, 37
 Super alloys, 50
 Surface finish, 77

T

Taylor tool life equation, 51
 T-303, 38
 Teflon, 38, 46
 Tips & tricks, 39, 63, 79
 Titanium, 52
 TiC, 68
 TE, 70
 Turning sets, 70
 Tool life, 51
 Toner cartridges, 52

U, V

Vacuum chamber, 43
 Vickers Hardness, 46

W

Wax, 53
 Wood, 54, 62
 Wiedemann-Franz, 46
 Wrought aluminum, 31
 Wire gauge, 47

X, Y

Yield strength, 78

Z, #

4-jaw independent chuck, 30
 A2, 48
 6061, 31
 7075, 31
 2011-T3, 32
 2024-T351, 32
 2024-T4, 32
 2024-T851, 32
 6061-T651, 32
 6061-T6511, 32
 6063-T52, 32
 6262-T6511, 32
 7075-T651, 32
 C36xxx, 34
 1018, 35
 C1018, 35
 C360, 38
 12L14, 38, 49, 60
 T-303, 38, 41
 SAE 316, 41
 UNS S31600, 41
 T-304, 41
 PTFE, 48
 6Al-4V ELI, 54